




Investigation of the Effect of the May 2008 Earthquake on Bridges in China

Original presentation in China by Dr. Banfu Yan of
Hunan University, Changsha, China

Presentation modified in Canada by
Dr. Atab Mufti, Dr. Baidar Bakht & Mr. Walter Saltzberg

Translation of Dr. Yan's presentation done by Mr. Cheng Zhang, M.Sc. Candidate
and Mr. Walter Saltzberg ISIS Consultant
University of Manitoba

Investigation of Earthquake-damaged Bridges in Guangyuan, Mianyang, and Deyang, Sichuan Province



Pictures of earthquake damage: May, 2008 by Dr. Banfu Yan of Hunan University


*Research Assistance: C. Zhang and M. Nayeem Uddin, MSc.Students,
University of Manitoba*

Information About Sichuan Province



Administration type:	Province
Capital: (and largest city)	Chengdu
Area:	485,000 km² (187,000 sq mi) (5th)
Population (2004) -Density	87,250,000 (3rd) 180 /km² (470 /sq mi) (22nd)
GDP (2006) - Per capita	CNY 863.8 billion (9th) CNY 10,574 (25th)
Industrial Base	Agriculture / Auto - Aerospace Manufacture






Picture from Wikipedia - Tectonic plates dividing the surface of the earth.


Indian Plate Movement

Indian Plate Movement

- It is currently moving northeast at 5 cm/yr (2 in/yr), while the Eurasian Plate is moving north at only 2 cm/yr (0.8 in/yr)
- It has covered a distance of 2,000 to 3,000 km (1,200 to 1,900 mi) in last 55 million years
- It moves faster than any other known plate
- This is causing the Eurasian Plate to deform, and the Indian Plate to compress



The Cause of Sichuan Earthquake



The convergence of the two plates is broadly accommodated by the uplift of the Asian highlands.



Earthquakes happen frequently in Sichuan Province. Released energy had been dissipated by Xianshuihe Fault.

Yangtze Plate


Longmenshan Fault, which was thought to be inactive, experienced a large movement on May 12, 2008.

The extent of the earthquake and after shock-affected areas lies north-east, along the **Longmenshan Fault**.

The fracture surface of Longmenshan Fault, stretching from Chengdu to Guangyuan, extended 240 km in length and was 30 km wide. This was the primary area affected by the earthquake disaster.



2008 Sichuan earthquake



Date: May 12, 2008

Magnitude: 8.0


Hypocentre Depth: 19 km

Epicentre: Wenchuan County
(Sichuan Province)

Aftershocks: over 7,000 total
aftershocks

Official figures (as of July 6, 2008 12:00 CST) state that **69,197** are confirmed dead, and **374,176** injured, with **18,340** listed as missing.

Earthquakes in China



Sichuan Earthquake

High frequency content, large (a,v,d) magnitude, shallow hypocenter, and near epicenter leads to serious earthquake damage

Sichuan earthquake aftermath



How are earthquakes measured?

- M-Scale Energy Release (Richter Scale)
- I-Scale Human Perception (MM-Modified Mercalli)
- a-Ground acceleration (Zones)

Relationship

$$I = 1.44M + F(R)$$

F is a decreasing function of R .

Empirical Relations

$$a = 1230 e^{0.8M} (R + 25)^{-2}$$

$$v = 15 e^M \left(R + 0.17 e^{0.59M} \right)^{-1.7}$$

$$\frac{ad}{v^2} = 1 + \frac{400}{R^{0.6}}$$

Here a , v and d are in cm/sec², cm/sec and cm

Practical Interest

$$\frac{ad}{v^2} = 5 \text{ to } 15$$

Tri-partite Graph for Sichuan Earthquake

Ground Motion Response Spectrum

According to empirical relations:

$$a = 1230e^{0.8M} (R + 25)^{-2} = 1230e^{0.8 \times 8.0} (80 + 25)^{-2} = 67.14 \text{ cm/sec}^2$$

$$v = 15e^{.M} (R + 0.17e^{0.59M})^{-1.7} = 15e^{8.0} (80 + 0.17e^{0.59 \times 8.0})^{-1.7} = 18.09 \text{ cm/sec}$$


Practical interest $d = \frac{6v^2}{a} = \frac{6 \times 18.09^2}{67.14} = 29.24 \text{ cm}$

SDF response spectrum

Using the form “spectrum amplification factors for horizontal elastic response”,

$$\left\{ \begin{array}{l} \text{Damp} = 5\% \\ \text{One Sigma (84.1\%)} \end{array} \right. \longrightarrow \left\{ \begin{array}{l} a = 2.71 \times 67.14 = 181.95 \text{ cm/sec}^2 \\ v = 2.30 \times 18.09 = 41.61 \text{ cm/sec} \\ d = 2.01 \times 29.24 = 58.77 \text{ cm} \end{array} \right.$$


Tripartite Graph of Sichuan Earthquake



Formation of the Response Spectrum for Sichuan Earthquake

No.	Period (s)	A (cm/s ²)	A (fraction of g)
1	0.01	67.14	0.7
2	0.09	67.14	0.7
3	0.6	67.14	0.7
4	0.9	67.14	0.7
5	1.69	67.14	0.7
6	6	18.94	0.2
7	8	14.21	0.1
8	9	12.63	0.1
9	10.16	11.19	0.1
10	20	2.89	0.0
11	30	1.28	0.0
12	40	0.72	0.0
13	50	0.46	0.0


Ground Motion Response Spectrum




Portage Creek Bridge, Victoria, B.C.



Portage Creek Bridge, British Columbia



(a)




(b)


(a) Pier No. 1 – Portage Creek Bridge (McKenzie Overpass)

(b) Pier No. 1 – Simplified Geometry

Portage Creek Bridge, British Columbia




(a) Plan of Portage Creek Bridge (McKenzie Overpass)




(b) Simplified Geometry of Portage Creek Bridge


**Finite Element Analysis
using SAP 2000**



Portage Creek Bridge



Portage Creek Bridge, British Columbia



Elastic response from SAP 2000 at the abutments and piers.

Measure Earthquakes

M-Scale	Energy Release	Richter
MM-Scale	Human Perception	Modified Mercallis
a-acceleration	Zones	Measured

All three are related to each other.


Sichuan Earthquake - May 12, 2008

Richter Magnitude - M	8.0
MM-Scale	XI
Acceleration- a	0.7g

Provided by the Dean of Engineering, Hunan University, Changsha, China - Professor Yan Xiao, Dr. Eng.

Seismic Intensity Scale

Intensity	Effects
1	People do not feel any Earth movement.
2	A few people might notice movement if they are at rest and/or on the upper floors of tall buildings.
3	Many people indoors feel movement. Hanging objects swing back and forth. People outdoors might not realize that an earthquake is occurring.
4	Most people indoors feel movement. Hanging objects swing. Dishes, windows, and doors rattle. The earthquake feels like a heavy truck hitting the walls. A few people outdoors may feel movement. Parked cars rock.
5	Almost everyone feels movement. Sleeping people are awakened. Doors swing open or close. Dishes are broken. Pictures on the wall move. Small objects move or are turned over. Trees might shake. Liquids might spill out of open containers.
6	Everyone feels movement. People have trouble walking. Objects fall from shelves. Pictures fall off walls. Furniture moves. Plaster in walls might crack. Trees and bushes shake. Damage is slight in poorly built buildings. No structural damage.
7	People have difficulty standing. Drivers feel their cars shaking. Some furniture breaks. Loose bricks fall from buildings. Damage is slight to moderate in well-built buildings; considerable in poorly built buildings.
8	Drivers have trouble steering. Houses that are not bolted down might shift on their foundations. Tall structures such as towers and chimneys might twist and fall. Well-built buildings suffer slight damage. Poorly built structures suffer severe damage. Tree branches break. Hillsides might crack if the ground is wet. Water levels in wells might change.
9	Well-built buildings suffer considerable damage. Houses that are not bolted down move off their foundations. Some underground pipes are broken. The ground cracks. Reservoirs suffer serious damage.
10	Most buildings and their foundations are destroyed. Some bridges are destroyed. Dams are seriously damaged. Large landslides occur. Water is thrown on the banks of canals, rivers, lakes. The ground cracks in large areas. Railroad tracks are bent slightly.
11	Most buildings collapse. Some bridges are destroyed. Large cracks appear in the ground. Underground pipelines are destroyed. Railroad tracks are badly bent.
12	Almost everything is destroyed. Objects are thrown into the air. The ground moves in waves or ripples. Large amounts of rock may move.



Qingchuan

Guangyuan

Beichuan


Mianzhu

Mianyang

Deyang

The road route

Cities in the Damage Zone



Many bridges span the waters between Qingchuan and Guangyuan. The damage to several bridges are discussed in the following slides.

State road 212 from Baolun to Shazhou



An aerial satellite photograph of the Bailonghu Reservoir. The reservoir is a large, dark blue body of water, partially enclosed by a dam structure. The surrounding terrain is rugged and mountainous, with various shades of brown, green, and grey. A network of roads and paths is visible, including a prominent road that runs along the right side of the reservoir. The overall scene depicts a natural landscape with significant human infrastructure.

State road 212
Bailonghu Reservoir

Image © 2008 DigitalGlobe
© 2008 Europa Technologies

Ganxihe Bridge



Ganxihe Bridge



Damage to the abutment walls



Damage to the abutment walls



Damage to the abutment walls



Damage
to deck



Baishui Bridge



Baishui Bridge



No visible damage middle arch





Crushing of concrete in spandrels





Movement of pylon







Crack in the deck




Crack in
abutment



Reason for the Damage

This reinforced concrete bridge appears to have had no significant damage to its main spans. However, due to large longitudinal movement during the earthquake, the short interior arches close to the abutments including expansion joints, suffered a lot of damage. Because of this, the bridge cannot be opened to traffic without major repairs.

Temporary Support for the Interior Arch





Jingtianba Bridge

Jingtianba Bridge



2008 5 17

Two-span arch bridge (each span 70m) collapsed closing provincial road 105



20m tall pier



20m tall pier




Interim Measures

There are a number of solutions for the replacement of this bridge on a temporary basis, which include: a military pontoon bridge, some other kind of temporary bridge, as well as relocation of the road, which will eliminate the need for the bridge.

Currently, the relocation of the road seems to be the most favourable solution.

Cities in the Damage Zone



Bridges spanning the waters between Beichuan and Mianyang

Anzhou Bridge



Anzhou Bridge

This is a two span arch bridge showing damage to various of its components.

It is hoped the bridge can be repaired.

Bridge before damage



Damage to K-brace



Deck is still in good condition



Interim Measures

1. In spite of the damage, the bridge is still open to traffic, with the following restrictions: the speed limit was reduced; the gross vehicle weight was reduced; and the traffic was directed to travel on the center of the bridge.
2. The bridge is to be inspected frequently to make sure there is no further damage to any of its components.

Xiangyangchun Bridge



Xiangyangchun Bridge is a short two-span bridge located on a curve, showing damage to various components. No assessment has yet been made regarding required repairs.



Showing the bottom of the deck which consist of precast voided concrete box girders



Broken pier cap



Movement of the expansion joint



Horizontal crack and movement of the abutment wall

Barrier wall moved



Nanba bridge under construction during earthquake



17 1:33AM

Collapsed girders



Cities in the Damage Zone

Mianzhu



Deyang

Bridges spanning the waters between Mianzhu and Deyang

Jinhua Bridge







Crack in abutment



Displacement between the bridge deck and road surface at an expansion joint

Reason for the Damage

The bridge survived the earthquake reasonably well. Most of the damage appears to have been caused by large horizontal forces as is evidenced by the damage to the short interior arch columns.

Wudu Mawei River Bridge





This bridge survived the earthquake very well. Damage was concentrated at the abutments, with one abutment having a movement of approximately 450 mm.



Bearing of one girder



Girder movement on the top of the pier cap

Reason for the Damage

Problem with rubber bearing was observed on some of the bridges. It appears that rubber bearings do not offer enough restraint to prevent girders from falling off the bearings during the sudden movements caused by the earthquake.

Mianzhu Lujiaoyan Bridge





Another example of damage as a result of sudden movements experienced during earthquakes

Guantong Bridge



Masonry arch bridge



Showing damage to the deck and railing on one side of the solid center of the bridge



Showing cracks at the bottom of the arch




Cracks at the top of the most interior arch

Reason for the Damage

Cracks at the bottom of the arch were caused by repeated back and forth horizontal movement during the earthquake.

Cracks at the top of the most interior arch were caused by the same movement, but were exaggerated by the resistance of the solid center main arch section.



**Thank You
Questions?**